AVIR END REFURBISHMENT KITTS



- Lower priced air repair solution*
- Includes the wearable components of seals and gaskets only**
- Available for all pump models
 - * Compared to what is included in our traditional Air End Kit
 - **Items highlighted in red in the exploded view





COST OF AIR END REPAIR	Complete Air End Repair Kit	Complete Air End Refurbishment Kit
Parts:	\$298	\$70
Labor, Down-Time, Lost Product:	\$1325	\$1325
Estimated Cost per Repair:	\$1623	\$1395
Annual Frequency of Repair:	1	1
Estimated Annual Cost:	\$1623	\$1395
Estimated Annual Savings:*	0	\$228

*Example Data: Repair = 1 hour • Pump model #: S05B2PBTPNI000

Repair labor rate fully burdened at \$125/hour • Lost product assumes paint.

Pricing subject to change.









MEW KITS AND THE PUMP MODELS THEY SUPPORTE

KIT#	PUMP MODELS
• 476.313.000	SB1, SB25, HDF1, HDF25
• 476.314.000	HDB1 1/2, HDB40, HDB2, HDF2, HDF3,
	HDF4, ST1 ½, ST40
• 476.315.000	HDB3, HDB4
• 476.316.000	HDF3-M, HDF4-M
• 476.317.000	ST1, ST25
• 476.318.000	S05 Metallic
• 476.319.000	S1F Metallic
• 476.320.000	S15 Metallic, S20 Metallic, S30 Metallic
• 476.321.000	PB 1/4
• 476.322.000	S05 Metallic with Polypropylene Mid-Section,
	S05 Non-Metallic, S07, S10
• 476.323.000	S1F Non-Metallic
• 476.324.000	S15, S20 Non-Metallic
• 476.325.000	S30 Non-Metallic

TO LEARN MORE, VISIT OUR WEBSITE OR CONTACT US TODAY

WWW.SANDPIPERPUMP.COM

Contact Your Distributor Today



Warren Rupp, Inc., A Unit of IDEX Corp. 800 N. Main Street Mansfield, OH 44901 USA Phone: 419.524.8388 Fax: 419.522.7867 WWW.SANDPIPERPUMP.COM



IDEX CORRORATION Distributed By: